
BAHA

ENGLISH VERSION

SPECIFICATIONS


: 6.95 m (22' 9 1/2")
: 6.20 m (20' 4")
: 5.50 m (18' 1/2")
...ximum beam
: 2.45 m (8')
Draught
Displacement
Outboard Maximum power
French Merchant Marine Standard V°: 2269
Class
Authorized N° of persons
Tonnage





DECK FITTINGS

- 1 Pulpit
- 2 Stanchion
- 3 Halyard (return) cheek-blocks
- 5Beaching-legstanchion 4 Mainsail and Genpa halyard jammers
- 6 Spinnaker and Genoa sheet winch 7 Aft mooring cleat
- 8 Rowlock
- 9 Backstay chainplate

- 10 Forward mooring cleat
  11 Mast step
  12 Spinnaker downhaul and topping lift halyard eyelet and cheek blocks
  13 Shrouds chainplates
- 14 Spinnaker boom downhaul and tooping lift jammers
  15 Jib track
- 16 Mainsheet chainplate
- 17 Spinnaker (return) turning-block bracket (or guard-lines depending on option\*) 18 Pushpit
- \* Pushpit and spinnaker figure as optional extras.







DROP KEEL MECHANISM

3 Raising pulley

2 Plate

Drop keel axle

1 Drop keel blocking jammers

Bracing brackets

Lowering pulley

Drop keel

OUTBOARD MOTOR BRACKET AS ON THE DRAWING TRANSOM TO STARBOARD FOR THE FITTING OF AN STRENGTHENING STRUTS ARE BUILT INTO THE AFT

BELOW

OUTBOARD BRACKET

WINCHES

The maintenance of winches must be carried out regularly. Here are a few hints which will allow you to keep your winches in good working order:

 $-\ 2$  or 3 times each season, dismantle the drums, clean and grease them. - At the end of the season, totally strip down, clean with petrol, grease them.

We advise your using white grease with Teflon.

This grease is particular in that it reduces friction and helps combat corrosion. It also has the advantage of being non-messy, non-toxic and bio-degradable.

# MAINTENANCE AND OUT-OF-SEASON STORAGE

#### MAINTENANCE

- Motor stop pull-knob - Gear box cover and works This should be carried out using products specially meant for marine Moving and mechanical parts must be regularly greased :

use (White Teflon grease).
Keep battery terminals in good condition.
Strip down and clean fuel filter from time to time.
For mechanics, refer to the maker's handbook and consult your approved dealer or stockist.

A frequent cleaning of hull and deck should be observed using (non-abrasive) cleaning agents (such as MIR in France) and fresh water. Should yellow stains appear, these can be easily removed with a clearer your dealer should be able to supply (such as SUPER DECAP in France). Be careful to rinse well.

For the hull, a yearly anti-fouling will avoid tiresome, time-consuming hull cleaning.

The GEL-COAT (exterior polyester) can be relied on to keep its appearance Against difficult staining on the waterline, muriatic acid can be used, after allowing the acid to work for 10 minutes, rinse thoroughly. For repairs, see attached notes.

Should an immediate an lasting problem arise, you should consult your dealer or JEANNIEAU S.A. directly.

### OUT-OF-SEASON STORAGE

In the case of a lengthy storage, great care must be taken to:
- rinse with fresh water
- oil and grease all metal parts
If the boat is to remain afloat, close all seacocks and protect all!
those parts which might rub or scrape...
If the boat has a stuffing-Dox, it is wise to lightly tighten it so
as to render it water-tight; do not forget to readjust it before the

next trip.

GOOD ADVICE AND CAREFUL MAINTENANCE REMAIN THE BEST GUARANTEE OF SAFE AND TROUBLE-FREE SAILING NEXT SEASON.

### CARE OF POLYESTER (G.R.P.)

yellow - etc. So that you may keep your boat looking as new, we have made available JEANNEAU factory constituants (parts and products) such as  $\operatorname{Gel-coat}$ :  $\operatorname{grey}$  -

#### INSTRUCTIONS FOR USE

### PRECAUTIONS TO BE TAKEN :

Temperature between 15°C and 25°C ( 59 F and 77 F

PROPORTIONS for polyester resin and Gel-coat :

Our products are preactivated. You need only to add the catalyst. (colourless liquid). The usual proportion is 2 parts in 100 (2 %). The pot-life (time product remains malleable) is about half an hour, hardening is complete after ten hours or so.

#### PROCEDURE :

rub down beforehand.

Prepare the amount of gel-coat necessary, preferably on a pane of glass.

To apply, use a spatula or sharp instrument.

Apply a liberal coat with a view to rubbing down with a wet'n'dry abrasive and to polishing to obtain a shiny surface. For minor retouching to smooth surfaces, simply apply a strip of sticky tape to the fresh gel-coat, then remove it after hardening to obtain a To fill a dent or scratch, clean over the surface with acetone, if necessary sniny surface.

#### STORAGE :

away from light.
Polyester is inflammable, take the necessary precautions.
BEMARE ! The catalyst is a dangerous product. Keep out of reach of children, keep clear of skin and muccus areas. In case of contact, wash thoroughly in soapy water and rinse well. So that they keep, you should keep the constituants in a cool, dry place

#### CLEANING :

Use acetone to clean all utensils.

### EVER AT YOUR SERVICE

## JEANNEAU AFTER-SALES SERVICE

It is stipulated that this document is not contractual and that the information given herein is merely guidance; we reserve the right to modify the specifications of boats without prior notice.

OWNER SERVICE RECORD